

## Car Images

**Car Front:**



**Car Back**



**Driver Side:**



**Passenger Side:**



**Front Interior:**




**4 Way Switch Driver Side**



**Corner Front Driver :**



**Corner Back Driver:**



**Corner Front Passenger:**




**Corner Back Passenger :**



**Rear Interior :**



**Trunk Open :**



**Car KM Reading :**



## Inspection Details :

**Enter Booking ID : 1718**

**Date & Time : 09/07/2025 2:30 PM**

**Inspection Expert Name : PARMINDER SINGH**

**Inspection Address : ASHOCK VIHAR**

**Inspection Expert City : New Delhi A**

**Lead Owner : 2**

**Customer Name : ADV SK**

**Pending Amount : 0**

**Customer Number: 852756155**

**OBD Scanning:Yes**

# Expert Details

**Inspection 45 Minutes Delayed? No**

**Your Photo with car number plate :**



## Car Details

**Car Company ? MERCEDES BENZ**

**Engine Capacity (in CC) ?1496**

**Car Registration Number ?DL2CAW4400**

**Transmission Type ? Automatic**

**Car Registration Year (Format: YYYY) ? 2016**

**Car Color ? WHITE**

**Car Variant? C-200**

**Car KM Current Reading ?29373**

**Car Registered State ? DELHI**

**Number of Car Keys Available ? 1**

**Car Registered City? DELHI**

**Chassis Number? WDD2050426L017125**

**Fuel Type ?Petrol**

**Engine Number? 27492030667987**

# Exterior Body

Driver Front Door ? Ok

Rear Number Plate? Ok

Driver - Front Fender ? Ok

Rear Bumper? Repainted

Driver - Front Door Window ? Ok

Boot Space Door/ Backdoor? Ok

Driver - Side View Mirror Housing ? Ok

Passenger - Back Door? Ok

Driver - Side View Mirror Glass ? Ok

Passenger - Back Door Window? Ok

Driver - Indicator Front? Ok

Fuel Filter Flap? Ok

Driver - Front Wheel Arch/ Fender Lining? Ok

Passenger Door Sill? Ok

Driver - Front Mud Flap? Ok

Passenger Back Quarter Panel? Ok

Driver - Front Cladding ? Ok

Passenger Front Door? Ok

Driver - Roof Rail ? Ok

Passenger Front Door Window? Ok

Driver - Door Sill ? Ok

Passenger Side View Mirror Housing? Ok

Driver -Back Door? Ok

Passenger Side View Mirror Glass? Ok

Driver - Back Door Window ? Ok

Passenger Front Indicator? Ok

Driver - Rear Cladding? Ok

Passenger Front Fender? Ok

Driver - Rear Wheel Arch / Fender Lining? Ok

Windshields? Ok

Driver - Back Mud Flap ? Ok

Match all Glasses Serial Number? Matching

Driver - Back Quarter Panel ? Ok

Front Bonnet Top ? okk

Driver - Back Indicated ? Ok

Front Grill? Repainted

Passenger - Back Indicated ? Ok

Fog Light's? okk

Rear Windshield? Ok

Driver Headlight? okk

Connected Taillights? Ok

Passenger Headlight? okk

Driver Taillights? Damaged

Front Number Plate? okk

Passenger Taillights? Ok

Car Roof Outside?

## Body Frame Accidental Checklist

Radiator Core Support ? OK

Driver Side Running Board? ok

**Match Chassis No Plate with the Real Body?  
Matching**

**Driver side Strut Tower Apron? ok**

**Passenger Strut Tower Apron? ok**

**Front Bonnet UnderBody? ok**

**Driver Side A Pillar? ok**

**Driver Side B Pillar? ok**

**Driver Side C Pillar? ok**

**Driver Side D Pillar ? ok**

**Boot Lock Pillar? ok**

**Boot Floor? ok**

**Passenger Side D Pillar? ok**

**Passenger Side C Pillar? ok**

**Passenger Side B Pillar? ok**

**Passenger Side A Pillar? ok**

**Passenger Side Running Board? ok**

## Engine (Before Test Drive)

**Car Start : Yes**

**Wiring :OK**

**Engine Oil Quality: Clean And  
Complete**

**Engine Oil Cap: Clean**

**Engine Mounting and Components : Ok**

**Coolant Level : Ok**

**Coolant Quality : Ok**

**Smoke Emission : Ok**

**AC Compressor Mounting : Ok**

**AC Fan Belt : Ok**

**Exhaust Pipe : Ok**

**Engine Fan Belt : Ok**

**Battery : Ok**

## OBD Scan

**Any Fault Code Present : No**

## OBD Scan Photo :



## Electrical And Interior

**Central Lock Working : Ok**

**Ignition Switch / Push Button :Ok**

**Driver - Front Indicator :Working**

**Passenger - Front Indicator : Working**

**Driver Headlight : Working**

**Passenger Headlight : Working**

**Driver Headlight Highbeam : Working**

**Passenger Headlight Highbeam : Working**

**Front Number Plate Light : Working**

**Driver Back Indicator : Working**

**Passenger Back Indicator : Working**

**Back Number Plate Light: Working**

**Brake Light Driver :Working**

**Brake Light Passenger : Working**

**Driver Tail Light : Working**

**Passenger Tail Light: Working**

**Steering Wheel Condition : OK**

**Steering Mountain Controls : Working**

**Back Camera : Working**

**Multi Function Display : Working**

**Car Horn : Working**

**Entertainment System : Working**

**Cruise Control: Working**

**Interior Lights : Working**

**Sun Roof : Working**

**Bonnet Release Operation: Working**

**Fual Cap Release Operation : Working**

**Check Onboard Computer ADBLue Level-  
Diesel Cars : Not Applicable**

**Window Safety Lock : Working**

**Driver ORVM Controls : Ok**

**Passenger ORVM Controls: OK**

**Glove Box : Ok**

**Wiper : Ok**

**Rear View Mirror : Ok**

**Dashboard Condition : Ok**

**Car Roof From Inside : Ok**

**Window Passenger Side: Working**

Reverse Parking Sensor : Working


Seat Adjustment Passenger Rear Side : Working

Check All Buttons (Mention if Anything not working ) :CAR ROOF NOISE AND SCRACHIES OUTER ROOF SIDE SPORTS MODE NOT WORKING

Multi Function Display (In Car On):



Multi Function Display (In Car Start): Car Roof From Inside Image :



## Air Conditioning

Air Conditioning Turning On : Ok

De Fogger Front Vent Working : Ok

AC Cool Temperature : 10

De Fogger rear Vent Working : Ok

AC Hot Temperature : 42

Air Conditioning All Vents : Ok

Air Condition Direction Mode Working : Ok

AC Abnormal Vibration : Not Present

AC Cool Mode Temperature :



AC HOT Mode Temperature :



## Tyres

Tyre Size : 17

Passenger Back Tyre Manufacturing Date :

Tyre Type : Tubeless

Passenger Back Tyre Shape : ok

Rim Type : Alloy

Passenger Front Tyre Depth Check : Bad

Driver Front Tyre Depth Check : Average

Passenger Front Tyre Manufacturing Date :

Driver Front Tyre Manufacturing Date : ok

Passenger Front Tyre Shape :

**Driver Front Tyre Shape : ok**

**Stepney Tyre Depth Check : Average**

**Driver Back Tyre Depth Check : Average**

**Stepney Tyre Manufacturing Date :**

**Driver Back Tyre Manufacturing Date :**

**Stepney Front Tyre Shape : ok**

**Driver Back Tyre Shape :ok**

**Sign of Camber Issue : Not Present**

**Passenger Back Tyre Depth Check : Bad**

**Driver Front Tyre Tread Depth :**



**Driver Back Tyre Tread Depth :**



**Passenger Back Tyre Tread Depth:**



**Passenger Front Tyre Tread Depth :**



**Stepney Tyre Depth Check :**



## Engine (After Test Drive)

**Check for oil leak near Engine : Not Present**

**Engine Noise : Not Present**

**Radiator Fan : Working**

**Radiator Condition : Ok**

**Smoke from dipstick point : Not Present**

**Transmission oil leakage : Not Present**

**Engine Vibration : Not Present**

**Hoses : Ok**

**Exhaust Sound : Not Present**

**Oil leak near Engine Image**

**:**



## Under Body

**Under Trays : Ok**

**Silencer : Ok**

**Front Protection Cover :Ok**

**Fuel Tank : Ok**

**Rear Protection Cover : Ok**

**Any Fuel Leaks under Body : Not Present**

## Equipment's

**Tool Kit : Present**

**Tool Kit Image :**



# Issue

**Any Issues Found in Car: CAR ROOF NOISE AND SCRACHIES OUTER ROOF SIDE SPORTS MODE NOT WORKING**

**Steering colom noise**

**Rear both tyre need change**

**Sport mord not working**

**Sunroof noise**

**Rear went flow less**

**Both bumper repainted**

**Rh side tail light broken**

**ODO METER IS TEMPERD**

**Photo of Issue :**



## Car Images From All Side

**Driver Front Door Photos :**



**Driver Front Fender Photos**



**Driver Front Door Window Photos**



**Driver - Side View Mirror Housing Photo's**



**Driver Side View Mirror Glass Photos :**



**Driver - Indicator Front Photos :**



**Driver - Front Wheel Arch/ Fender Lining Photos**



**Driver - Mud Flap Photos :**



**Driver - Front Cladding Photos**



**Driver - Roof Rail:**



**Driver -Door Shill:**



**Driver - Back Door Photos:**



**Driver -Rear Cladding:**



**Driver - Rear Wheel / ARCH/Fender Lining**

**Photos:**



**Driver -Back Mud Flap**

**Photos:**



**Driver - Back Quarter Panel Photo's**



**Driver -Back Indicator Photos:**



**Passenger - Back Indicator Photo's**



**Rear Whindshield Photos**



**Connected Taillight Photos**



**Driver Traillights Photos :**



**Passengers Traillights Photos :**



**Rear Number Plate Photos Rear Bumper Photos**



**Boot Space Door/ Backdoor Photo's :**



**Passenger - Back Door Photo's :**



**Passenger - Back Door Window Photos :**



**Fuel Filter Flap Photo's**



**Passenger Door Sill Photos :**



**Passenger Back Quarter Panel Photo's :**



**Passenger Front Door Photo's**



**Passenger Front Door Window Photo's :**





**Passenger Side View Mirror Housing Photos :**



**Passenger Side View Mirror Glass Photo's**



**Passenger Front Indicator :**



**Passenger Front Fender**



**Windshields :**



**Front Bonnet Top Photos**



**Front Grill Photo's :**



**Fog Light's Photo's :**



**Driver Headlight Photos:**



**Passenger Headlight Photos:**




**Front Number Plate :**




**Car Roof Outside Photo's**




**Paasenger Side :**



**Front Intirior:**



**4 Way Switch Driver :**



**Corner Front Driver :**



**Corner Back Driver :**



**Corner Back Passenger :**



**Corner Front Passenger :**



**Rear Interior :**



**Trunk Open :**



**Car KM Reading :**



**Photo of Issue**




**Underbody Left :**



**Underbody Rear:**



**Underbody Front :**



**Underbody Right :**



**Radiator Core Support Image**



**Driver side Strut Tower Apron Image**



**Passenger side Strut Tower Apron Image**



**Front Bonnet UnderBody image**



**Driver side A Pillar Image**



**Driver side B Pillar Image**



**Driver side C Pillar Image**

**Driver side D Pillar Image**


**Driver side Running Board Image**



**Boot Lock Pillar Image**

**Bopot Floor Image**

**Paasenger Side D Pillar Image**



**Paasenger Side C Pillar Image**

**Paasenger Side B Pillar Image**

**Paasenger Side A Pillar Image**



**Paasenger Side Running Board Image**



**Note:** While inspecting the vehicle, our boy will be responsible as long as he is at the inspection site, after that he will not be responsible even if anything happens to the vehicle

