

Car Images:

Car Front:



Car Back:



Driver Side:



Passenger Side:



Front Interior :



Underbody Left:



Underbody Rear:



Underbody Front :



Underbody Right:



Inspection Details :

Enter Booking ID : 1698

**Inspection Address :
MAHINDRA JANAKPURI**

**Assigned Expert Name
:PARMINDER SINGH**

Lead Owner : 1

**Inspection Expert City : New
Delhi A**

Pending Amount : 0

Customer Name : HIMANSHU

OBD Scanning:No

**Customer Number:
9873263245**

**Date & Time : 08/26/2025 1:00
PM**

Car Details

Car Company ? MAHINDRA

Engine Capacity (in CC) ?

**Chassis
Number? MA1VP271BS6H91390**

Car Variant? XEV 9E

Transmission Type ?

Car Registered State ? DELHI

Car Color ? GOLD

Car Registered City? DELHI

Car KM Current Reading ?65

Fuel Type ?

**Number of Car Keys Available
? 2**

Exterior Body

Driver Front Door ? Ok

**Driver - Back Quarter Panel ?
Ok**

**Passenger Side View Mirror
Housing? Ok**

Driver - Front Fender ? Ok

Driver - Back Indicated ? Ok

**Passenger Side View Mirror
Glass? Ok**

**Driver - Front Door Window ?
Ok**

**Passenger - Back Indicated ?
Ok**

Passenger Front Indicator? Ok

**Driver - Side View Mirror
Housing ? Ok**

Rear Windshield? Ok

Passenger Front Fender? Ok

**Driver - Side View Mirror Glass
? Ok**

Connected Taillights? Ok

Windshields? Ok

Driver - Indicator Front? Ok

Driver Taillights? Ok

**Match all Glasses Serial
Number? Matching**

**Driver - Front Wheel Arch/
Fender Lining? Ok**

Passenger Taillights? Ok

Rear Number Plate? Ok

Front Bonnet Top ? okk

Driver - Front Mud Flap? Ok	Rear Bumper? Ok	Front Grill? okk
Driver - Front Cladding ? Ok	Boot Space Door/ Backdoor? Ok	Fog Light's? okk
Driver - Roof Rail ? Ok	Passenger - Back Door? Ok	Driver Headlight? okk
Driver - Door Sill ? Ok	Passenger - Back Door Window? Ok	Passenger Headlight? okk
Driver -Back Door? Ok	Charger Flap? Ok	Front Number Plate? okk
Driver - Back Door Window ? Ok	Passenger Door Sill? Ok	Car Roof Outside?
Driver - Rear Cladding? Ok	Passenger Back Quarter Panel? Ok	
Driver - Rear Wheel Arch / Fender Lining? Ok	Passenger Front Door? Ok	
Driver - Back Mud Flap ? Ok	Passenger Front Door Window? Ok	

Battery , Charger and Hood

Charger Output (KilloWatts) : OK	Mooter Coolent Level : Ok	Cables: Ok
Charger: Working	Mooter : Ok	Fuse Box: Ok
Charger Port : Working	Abnormal Motor Noise : Not Present	Auxilliary Battery: Ok
Betry Chrging On Connecting Phone : Not Able to Check	Motor Manufacturing Date :	

Body Frame Accidental Checklist

Radiator Core Support ? OK	Driver Side B Pillar? ok	Passenger Side D Pillar? ok
Match Chassis No Plate with the Real Body? Matching	Driver Side C Pillar? ok	Passenger Side C Pillar? ok
	Driver Side D Pillar ? ok	Passenger Side B Pillar? ok

Driver side Strut Tower
Apron? ok

Driver Side Running
Board? ok

Passenger Side A Pillar? ok

Passenger Strut Tower Apron? ok
Boot Lock Pillar? ok

Passenger Side Running
Board? ok

Boot Floor? ok

Front Bonnet UnderBody? ok

Driver Side A Pillar? ok

Electrical And Interior

Central Lock Working : Ok
Ignition Switch / Push
Button :Ok

Brake Light Passenger :
Working

Bonnet Release Operation:
Working

Driver - Front Indicator
:Working

Driver Tail Light : Working

Fual Cap Release
Operation : Working

Passenger - Front
Indicator : Working

Passenger Tail Light:
Working

Window Safety Lock :
Working

Driver Headlight : Working

Steering Wheel Condition :
OK

Driver ORVM Controls : Ok

Passenger Headlight :
Working

Steering Mountain
Controls : Working

Passenger ORVM Controls:
OK

Driver Headlight
Highbeam : Working

Back Camera : Working

Glove Box : Ok

Passenger Headlight
Highbeam : Working

Reverse Parking Sensor :
Working

Wiper : Ok

Front Number Plate Light :
Working

Multi Function Display :
Working

Rear View Mirror : Ok

Driver Back Indicator :
Working

Car Horn : Working

Dashboard Condition : Ok

Passenger Back Indicator :
Working

Entertainment System :
Working

Car Roof From Inside : Ok

Driver Back Indicator :
Working

Cruise Control: Working

Window Passenger Side:
Working

Passenger Back Indicator :
Working

Interior Lights : Working

Seat Adjustment
Passenger Rear Side :
Working

Back Number Plate Light:
Working

Sun Roof : Working

Check All Buttons
(Mention if Anything not
working) :OK

:Working

Multi Function Display (In Car On):



Multi Function Display (In Car Start):



Car Roof From Inside Image :



Air Conditioning

Air Conditioning Turning On : Ok

Air Condition Direction Mode Working : Ok

De Fogger rear Vent Working : Ok

AC Cool Temperature : 8

AC Abnormal Vibration : Not Present

Air Conditioning All Vents : Ok

AC Hot Temperature : 40

De Fogger Front Vent Working : Ok

Tyres

Tyre Size : 19

Driver Back Tyre Manufacturing Date : {3025

Passenger Front Tyre Shape :

Tyre Type : Tubeless

Driver Back Tyre Shape :ok

Stepney Tyre Depth Check : Good

Rim Type : Alloy

Passenger Back Tyre Depth

Driver Front Tyre Depth Check : Good

Passenger Back Tyre Manufacturing Date : {3025

Stepney Tyre Manufacturing Date : 3025

Driver Front Tyre Manufacturing Date : {3025

Passenger Back Tyre Shape : ok

Stepney Front Tyre Shape : ok

Driver Front Tyre Shape : ok

Driver Back Tyre Depth Check : Good

Passenger Front Tyre Depth Check : Good

Sign of Camber Issue : Not Present

Passenger Front Tyre Manufacturing Date : {3025

Under Body

Under Trays : Ok

Silencer : ok

Front Protection Cover :Ok

Fuel Tank :

Rear Protection Cover : Ok

Any Fuel Leaks under Body :

Equipment's

Tool Kit : Present

Tool Kit Image :



Issue

Any Issues Found in Car: CAR IS OK

Photo of Issue:



Car Images From All Side

Driver Front Tyre Tread Depth :



Driver Back Tyre Tread Depth :



Passenger Back Tyre Tread Depth



Passenger Front Tyre Tread Depth



Stepney Tyre Depth Check Car Roof From Inside :



Driver Front Door Photos : Driver Front Fender Photos



Driver Front Door Window Photos



Driver - Side View Mirror Housing Photo's



Driver Side View Mirror Glass Photos :



Driver - Indicator Front Photos :



Driver - Front Wheel Arch/ Fender Lining Photos



Driver - Mud Flap Photos :



Driver - Front Cladding Photos



Driver - Roof Rail:



Driver -Door Shill:



Driver - Back Door Photos:



Driver -Rear Cladding:



Driver - Rear Wheel / ARCH/Fender Lining

Photos:



Driver -Back Mud Flap

Photos:



Driver - Back Quarter Panel Photo's



Driver -Back Indicator Photos:



Passenger - Back Indicator Photo's



Rear Whindshield Photos



Connected Taillight Photos



Driver Traillights Photos :



Passengers Traillights Photos :



Rear Number Plate Photos :



Rear Bumper Photos



Boot Space Door/ Backdoor Photo's :



Passenger - Back Door Photo's :



Passenger - Back Door Window Photos :



Charger Flap Photos



Passenger Door Sill Photos :



Passenger Back Quarter Panel Photo's :



Passenger Front Door Photo's



Passenger Front Door Window Photo's :



Passenger Side View Mirror Housing Photos :



Passenger Side View Mirror Glass Photo's



Passenger Front Fender



Windshields :



Front Bonnet Top Photos



Front Grill Photo's :



Fog Light's Photo's :



Driver Headlight Photos:



Passenger Headlight Photos:



Front Number Plate :



Car Roof Outside Photo's



Radiator Core Support Image

Driver side Strut Tower Apron Image






Passenger side Strut Tower Apron Image



Driver side A Pillar Image Driver side B Pillar Image



Driver side C Pillar Image



Driver side D Pillar Image



Driver side Running Board Image



Boot Lock Pillar Image




Boot Floor Image




Paasenger Side D Pillar Image




Paasenger Side C Pillar Image



Paasenger Side B Pillar Image



Paasenger Side A Pillar Image





Paasenger Side Running Board Image

Charger Image

Charger Port Image



Note: While inspecting the vehicle, our boy will be responsible as long as he is at the inspection site, after that he will not be responsible even if anything happens to the vehicle